Oil Field Environmental Incident Summary

Incident: 20150207184027 Date/Time of Notice: 02/07/2015 18:40

Responsible Party: Continental Resources

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: BEULAH CTB

Field Name: MEDICINE POLE HILLS Well File #:

Time Incident: 06:00 Date Incident: 2/7/2015 Facility ID Number: 405456-03 **BOWMAN** Rna: 104 Sec: 4 County: **Twp:** 129 Qtr: NW NW

Location Description:

Submitted By: Todd Senescall Received By:

Contact Person: Terry Straub

PO BOX 268870

OKLAHOMA CITY, OK 73126

General Land Use: Pasture Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: No Reported to NRC: No

> Spilled Units Recovered Units Followup **Units** barrels

Barrels Oil 1

Brine

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 12/21/2016 Clean Up Concluded: 2/10/2015

Risk Evaluation:

fire

Areal Extent:

Approximately 0.4 acres of pasture was lightly misted by oil.

Potential Environmental Impacts:

soil, vegetation

Action Taken or Planned:

Fire dept. notified and responded. Clean up plans will be discussed with landowner.

Wastes Disposal Location: TBD

Agencies Involved: Local Fire Department-Rhame

Area & Oncall NDIC Inspectors-Matt Tibor, Monica Rolls (left messages)

Updates

Date: 2/9/2015 Status: Reviewed - Follow-up Required Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill impacted the surrounding area. Followup is necessary.

Date: 6/9/2015 Status: Inspection Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

6/9/2015 at 15:32, on location. Met with site personnel who pointed out location of incident. Mist came out of tanks at southwest corner of facility due to programming error. Visible residue on fence line to the southwest of the tanks. Some scraping appears to have been performed, as there are many erosion blankets and wattles off location in the adjacent pasture land drainage to the southwest. Standing water from recent rains shows no visible sheen, vegetation in drainage is growing, some of the scraped parts have not yet fully recovered but no visible staining on the vegetation or dirt.

Date: 3/9/2016 Status: Correspondence Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Bill Suess sent a No Further Action letter dated March 9, 2016.